

Afhjælpning af Dell PC BIOS sårbarhed

Det har for nyligt vist sig at stort set alle Dell PC'er leveret siden 2009 har en sårbarhed i BIOS driveren, som betyder at hackere vil kunne overtage PC'en. Da sårbarheden lige er opdaget er der ikke endnu set forsøg på at udnytte denne sårbarhed, men det må stærkt anbefales at få opdateret Dell BIOS snarest.

Opdateringen er meget simpel og tager kun få minutter. Se beskrivelse herunder.

Installation af opdatering

1. gå til Dell website: <https://www.dell.com/support/kbdoc/da-dk/000186019/dsa-2021-088-dell-client-platform-security-update-for-dell-driver-insufficient-access-control-vulnerability>

The screenshot shows the Dell support website interface. At the top, there is a navigation bar with the Dell logo, 'Dell Technologies', a search bar, and links for 'Log på' and 'Indkøbsvogn'. Below this is a secondary navigation bar with categories like 'Produkter', 'Løsninger', 'Services', 'Support', and 'Community'. The main content area displays the article title 'DSA-2021-088: Dell Client Platform Security Update for an Insufficient Access Control Vulnerability in the Dell dbutil Driver'. A summary states: 'Oversigt: Dell released an update utility to mitigate a security vulnerability affecting the dbutil_2_3.sys driver packaged with Dell Client firmware update utility packages and tools.' On the left, there is a sidebar with navigation options: 'ARTIKELINDHOLD', 'JURIDISKE OPLYSNINGER', 'EGENSKABER FOR ARTIKEL', and 'BEDØM DENNE ARTIKEL'. The main content area includes a table with the following data:

Proprietary Code CVE	Description	CVSS Base Score	CVSS Vector String
CVE-2021-	Dell <i>dbutil_2_3.sys</i> driver contains an insufficient access control vulnerability which	8.8	CVSS:3.1/AV:L/AC:L/PR:L/UI:N/SC/CH/I/H/A/H

2. Klik på option 1 'Dell Security Advisory Update – DSA-2021-088

Step 1: Immediately remove the vulnerable *dbutil_2_3.sys* driver from the affected system using one of the options below. NOTE: If you are using the Dell System Inventory Agent you must first download the latest available version (2.6.0.0 or greater) [here](#).

- Option 1 (Recommended): Download and run the [Dell Security Advisory Update – DSA-2021-088](#) utility.
- Option 2: Manually remove the vulnerable *dbutil_2_3.sys* driver:

Step 1: Check the following locations for the *dbutil_2_3.sys* driver file:

3. Tryk på 'Herunterladen' – der hentes nu en .EXE fil, som startes

The screenshot shows the Dell Support website interface. At the top, there is a navigation bar with the Dell logo, 'DELLTechnologies', a search bar, and links for 'Log på' and 'Warenkorb'. Below the navigation bar, there are tabs for 'Produkte', 'Lösungen', 'Services', 'Support', and 'Community'. The main content area is titled 'Dell Security Advisory Update - DSA-2021-088'. It contains a section for downloading the latest driver, a table of updates, and a 'Herunterladen' button circled in red.

Erhalten Sie den neuesten Treiber
Bitte geben Sie Ihre Produktdetails ein, um die neuesten Treiberinformationen für Ihr System anzuzeigen. [Details eingeben](#)

Fehlerkorrekturen und Verbesserungen
This update provides a remedy for Dell Security Advisory DSA-2021-088. It will detect and uninstall the dbutil_2.3.sys driver from the system.
An enhanced version of the tool is planned for availability on May 10 to enhance features for enterprise customers.
Upcoming enhancements:
Support for deploying through Dell System Management solutions
Enhanced logging capabilities
Ability to run against multiple drives
Enhanced exit codes

Version	Kategorie
Version 1.0.0, A00	Sicherheit

Veröffentlichungsdatum:
04 Mai 2021

Wichtigkeit
[Empfohlen](#)

Verfügbare Formate

Dateiformat:	Update-Paket für Microsoft Windows 32-Bit
Dateiname:	Dell-Security-Advisory-Update-DSA-2021-088_7PR57_WIN_1.0.0_A00.EXE
Download-Art:	HTTP
Dateigröße:	7.9 MB
Beschreibung des Dateiformats:	Dell Update Packages (DUP) im Microsoft Windows 32-Bit-Format können auch unter Microsoft Windows 64-Bit-Betriebssystemen ausgeführt werden. Dell Update Packages (DUP) im Microsoft Windows 64-Bit-Format hingegen können nur unter Microsoft Windows 64-Bit-Betriebssystemen ausgeführt werden. Stellen Sie bei der Auswahl eines Gerätetreiberupdates sicher, dass Sie das für Ihr Betriebssystem passende Update wählen.

[Herunterladen](#)

4. Vælg INSTALL

The screenshot shows the Dell Update Package installation window. The window title is 'Dell Update Package'. The main content area displays the update details: 'Dell Security Advisory Update - DSA-2021-088 v1.0.0 (A00) April 29, 2021'. Below the details, there are two buttons: 'INSTALL' and 'EXTRACT'. The 'INSTALL' button is highlighted in blue, and the 'EXTRACT' button is greyed out.

Dell Update Package


Dell Security Advisory Update - DSA-2021-088
v1.0.0 (A00) April 29, 2021

Install or update your system with this software [INSTALL](#)


Only extract contents of software update [EXTRACT](#)

© 2009 - 2021 Dell Inc. All rights reserved.

5. Skriv 'y'



6. Det tager ca 1 minut, så er installationen færdig



7. Nu er din PC beskyttet